

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General							
Zone		Ward No.		Ward Name			
YELAHANKA		6		Thanisandra			
Street ID		Street Name		Significant Landmark			
W1140		6th Main Rd		R.K.HEGDE NAGAR MAIN ROAD			
Segment No.		Total Length (m)					
6/S-W1140/S084337		121.07					
Segment Details							
Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	121.07	77.629433	13.046594	77.628418	13.047049	RI-A07	W1763
Work Details							
History of Road / Lane / Circles							
Name of the Work		Sanctioned Estimated Amount (Rs.)			Sanctioned Year		
Construction of immersion tank for lard Ganesha idols at near Rachenahalli Lake in ward no 06 Byatarayanapura Sub-Division Yelahanka zone (Modified wo		2000000			2016		
Year	Type of Work			Other Work Type			
2016 - 2017	Asphalting						
Tender	Work Details			Job No. / Work Code			
Tender	Construction of immersion tank for lard Ganesha idols at near Rachenahalli Lake in ward no 06 Byatarayanapura Sub-Division Yelahanka zone (Modified work to construction of culvert)			006-15-000006			
Work Order No.	Work Order Date			Period of Extention			
EE/BTP/BBMP/E-PMT/WO/80/2016-17	26/07/2016			60 DAYS			
Defect Liability Period From	Defect Liability Period To			Multiple road involved with the same Job No/ Work Code #			
26/07/2016	25/07/2017			Yes			
Contractor Details							
Name of Contractor		Contractor Reg No (BBMP/PWD)			Expenditure Booked \ Released (Rs)		
M.B.HOMBAL					0.00		
Phone No.		E-Mail ID					
9900083697							

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W1140

Field Inspection Details**Number of Trees**

3

Any Other Information**Name**

KRISHNAPPA

Date of Inspection

28/10/2016

Remarks

COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA**Ward No:** 6**Ward Name:** Thanisandra**Street ID:** W1140**Date:** 28/10/2016**Time:** 21:29:18**RH** 20161028212918**Page** 2 **of** 3

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks				
Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	28/10/2016	27/11/2016	COMPLETED
SE	VASU K M	28/10/2016	27/11/2016	COMPLETED
EE	YARAPPA REDDY	28/10/2016	27/11/2016	COMPLETED
AEE	J N LOKESH	28/10/2016	27/11/2016	COMPLETED
AE	KRISHNAPPA	28/10/2016	27/11/2016	COMPLETED
AE	KRISHNAPPA	28/10/2016	27/11/2016	COMPLETED